


Static electricity can be used to “pin” the film to the last steel cylinder before the winder. This will prevent the web from moving laterally from side to side and causing a bad reel.

The same technique is used on cast film lines to prevent the film shrinking (or neck-in) when it touches the chill roller.

There is no need to “pin” the whole web to the cylinder - you only need to pin the edges.

Edge Pinning on a winder



7080 Bar and 7300 Generator